

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_RD0827_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 827 has a copy of the levee manuals.					

No Photos

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_RD0827_01_s_2013_7				
Comment Code					
Inspector Comment					
RD 827 shares a maintained stockpile of Flood Response Material with RD 785.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_RD0827_01_f_2014_9				
Comment Code					
Inspector Comment					
RD 827 works jointly with RD 785 on Flood Preparedness and Training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start	0.04	Rating **	A/W	Issue No.	6
LM End	0.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.674833 °	38.674833 °
				-121.630039 °	-121.630039 °
DWR ID	DWR_RD0827_01_s_2018_6				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Small rills beginning to form on waterside slope. Recommend monitoring.					

Photo 1 of 1 : SP_2019_RD0827_187_6_20190304_00004.jpg



View of rills on the waterside slope. Spring 2018.

LM Start	0.45	Rating **	M	Issue No.	8
LM End	0.45	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.670638 °	38.670638 °
				-121.624652 °	-121.624652 °
DWR ID	DWR_RD0827_01_s_2018_8				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree on the waterside slope.					

No Photos

LM Start	0.51	Rating **	M	Issue No.	13
LM End	0.51	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.669929 °	38.669929 °
				-121.623776 °	-121.623776 °
DWR ID	DWR_RD0827_01_s_2016_13				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Rills caused by rain.					

Photo 1 of 2 : SP_2019_RD0827_187_13_20190304_00009.jpg



View of the erosion on the landward side of the levee looking downstream. Spring 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start	0.51	Rating **	M	Issue No.	13 (cont)	
LM End	0.51	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.669929 °		38.669929 °
				-121.623776 °		-121.623776 °
DWR ID	DWR_RD0827_01_s_2016_13					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Rills caused by rain.						

Photo 2 of 2 : SP_2019_RD0827_187_13_20190304_00010.jpg



View of runoff erosion site. LS slope. Fall 2016.

LM Start	0.61	Rating **	A/W	Issue No.	22
LM End	0.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.668873 °	38.665750 °
				-121.622513 °	-121.618523 °
DWR ID	DWR_RD0827_01_s_2012_22				
Comment Code					
V8 : Environmental Requirements.					
Inspector Comment					

Photo 1 of 2 : SP_2019_RD0827_187_22_20190304_00013.jpg



Revegetation site spring 2012.

LM Start	0.61	Rating **	A/W	Issue No.	22 (cont)
LM End	0.92	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2019_RD0827_187_22_20190304_00014.jpg



View of the revegetation site on the waterward side of the levee looking downstream. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start	1.00	Rating **	M	Issue No.	15
LM End	1.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.664920 °	38.664720 °
				-121.617557 °	-121.617318 °
DWR ID	DWR_RD0827_01_s_2017_15				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Prunings and fallen tree limbs on waterside levee slope.					

No Photos

LM Start	1.02	Rating **	A/W	Issue No.	18
LM End	1.02	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.664690 °	38.664690 °
				-121.617266 °	-121.617266 °
DWR ID	DWR_RD0827_01_f_2018_18				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
Minor runoff on the waterside slope. Recommend monitoring.					

No Photos

LM Start	1.09	Rating **	M	Issue No.	17
LM End	1.09	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.663946 °	38.663946 °
				-121.616453 °	-121.616453 °
DWR ID	DWR_RD0827_01_s_2019_17				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff site through rodent holes.					

Photo 1 of 1 : SP_2019_RD0827_187_17_20190311_00018.jpg



View of erosion on the waterside slope. Spring 2019.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start	1.12	Rating **	M	Issue No.	19
LM End	1.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.663572 °	38.663572 °
				-121.616087 °	-121.616087 °
DWR ID	DWR_RD0827_01_s_2019_19				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree on waterside slope.					

No Photos

LM Start	1.12	Rating **	M	Issue No.	3
LM End	1.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.663542 °	38.663542 °
				-121.616056 °	-121.616056 °
DWR ID	DWR_RD0827_01_f_2016_3				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion on the crown and waterside slope from runoff.					

Photo 1 of 3 : SP_2019_RD0827_187_3_20190304_00001.jpg



View of erosion on waterside levee slope. Spring 2017.

LM Start	1.12	Rating **	M	Issue No.	3 (cont)
LM End	1.12	Issue Type +	Ma	Location *	WS

Photo 2 of 3 : SP_2019_RD0827_187_3_20190304_00002.jpg



Another view of erosion on levee slope. A hole on the waterside slope has widened due to runoff. Spring 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start	1.12	Rating **	M	Issue No.	3 (cont)	
LM End	1.12	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.663542 °	38.663542 °	
				-121.616056 °	-121.616056 °	
DWR ID	DWR_RD0827_01_f_2016_3					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Erosion on the crown and waterside slope from runoff.						

Photo 3 of 3 : SP_2019_RD0827_187_3_20190304_00003.jpg



View of erosion on crown continuing to WS slope. Fall 2016.

LM Start	1.14	Rating **	A/W	Issue No.	14
LM End	1.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.663377 °	38.663377 °
				-121.615895 °	-121.615895 °
DWR ID	DWR_RD0827_01_s_2017_14				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Minor erosion on waterside slope. Recommend monitoring					

Photo 1 of 1 : SP_2019_RD0827_187_14_20190304_00011.jpg



View of erosion on waterside levee slope. Spring 2017.

LM Start	1.21	Rating **	M	Issue No.	11
LM End	1.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.662546 °	38.662546 °
				-121.615083 °	-121.615083 °
DWR ID	DWR_RD0827_01_s_2017_11				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree limbs on waterside levee slope.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.34	03/07/2019 03/07/2019	Zach Jojola

LM Start	1.30	Rating **	M	Issue No.	4
LM End	1.30	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Encroachments		38.661485 °	38.661485 °	
			-121.614006 °	-121.614006 °	
DWR ID	DWR_RD0827_01_s_2017_4				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Fallen tree limbs on waterside levee slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	03/05/2019 03/05/2019	Zach Jojola

LM Start	0.15	Rating **	A/W	Issue No.	10	
LM End	0.16	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			38.674778 °	38.674583 °	
				-121.642806 °	-121.642722 °	
DWR ID	DWR_RD0827_02_f_2017_10					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:200						
Site Designation:RD 827-02						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/6/2017						
Notes: no damage visible, ws armored with riprap						

Photo 1 of 3 : LEVAL_SP_2019_200_1239.jpg



LM Start	0.15	Rating **	A/W	Issue No.	10 (cont)
LM End	0.16	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL_SP_2019_200_1245.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
---	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**


Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	03/05/2019 03/05/2019	Zach Jojola

LM Start	0.15	Rating **	A/W	Issue No.	10 (cont)	
LM End	0.16	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	2017 Storm Damage			38.674778 °	38.674583 °	
				-121.642806 °	-121.642722 °	
DWR ID	DWR_RD0827_02_f_2017_10					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:200						
Site Designation:RD 827-02						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/6/2017						
Notes: no damage visible, ws armored with riprap						

Photo 3 of 3 : LEVAL_SP_2019_200_1246.jpg



LM Start	1.94	Rating **	M	Issue No.	8
LM End	1.96	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.652232 °	38.651939 °
				-121.627264 °	-121.627088 °
DWR ID	DWR_RD0827_02_s_2019_8				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
100' sloughing section on the landside slope. Exposed scarp is approximately 1' at the worst section. LMA placed visqueen over the issue.					

Photo 1 of 1 : SP_2019_RD0827_188_8_20190311_00026.jpg



View of sloughing on the landside slope. Spring 2019.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	03/05/2019 03/05/2019	Zach Jojola

LM Start	2.09	Rating **	U	Issue No.	7
LM End	2.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.650245 °	38.649602 °
				-121.626036 °	-121.625646 °
DWR ID	DWR_RD0827_02_s_2019_7				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Sloughing from 2019 storm damage. LMA placed visqueen over the issue.					

Photo 1 of 1 : SP_2019_RD0827_188_7_20190311_00025.jpg



View of sloughing on the landside slope. Spring 2019.

LM Start	2.62	Rating **	M	Issue No.	6
LM End	2.62	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.643375 °	38.643375 °
				-121.621776 °	-121.621776 °
DWR ID	DWR_RD0827_02_s_2018_6				
Comment Code					
DE : Debris					
Inspector Comment					
Fridge on the waterside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	03/05/2019 03/05/2019	Zach Jojola

LM Start	2.72	Rating **	M	Issue No.	13
LM End	2.73	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.642139 °	38.642028 °
				-121.620750 °	-121.620667 °
DWR ID	DWR_RD0827_02_f_2017_13				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:199					
Site Designation:RD 827-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/6/2017					
Notes: landside. Sloughing on the landside slope near pump.					
Movement has stabilized and the LMA will be constructing a setback levee within the next 3 years. Recommend monitoring.					

Photo 1 of 4 : SP_2019_RD0827_188_13_20190311_00024.jpg



View of sloughing on the landside slope. Spring 2019.

LM Start	2.72	Rating **	M	Issue No.	13 (cont)
LM End	2.73	Issue Type +	Ma	Location *	

Photo 2 of 4 : LEVAL_SP_2019_199_1231.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	03/05/2019 03/05/2019	Zach Jojola

LM Start	2.72	Rating **	M	Issue No.	13 (cont)
LM End	2.73	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			38.642139 °	38.642028 °
				-121.620750 °	-121.620667 °
DWR ID	DWR_RD0827_02_f_2017_13				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:199					
Site Designation:RD 827-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:6/6/2017					
Notes: landside. Sloughing on the landside slope near pump.					
Movement has stabilized and the LMA will be constructing a setback levee within the next 3 years. Recommend monitoring.					

Photo 3 of 4 : LEVAL_SP_2019_199_1232.jpg



LM Start	2.72	Rating **	M	Issue No.	13 (cont)
LM End	2.73	Issue Type +	Ma	Location *	

Photo 4 of 4 : LEVAL_SP_2019_199_1234.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2019

Reclamation District No. 0827 Elkhorn

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Left	2.78	03/05/2019 03/05/2019	Zach Jojola

LM Start	2.72	Rating **	A/W	Issue No.	14
LM End	2.72	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.642018 °	38.642018 °
				-121.620944 °	-121.620944 °
DWR ID	DWR_RD0827_02_s_2017_14				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Sloughing on the landside slope near pump. Movement has stabilized.					

Photo 1 of 2 : SP_2019_RD0827_188_14_20190304_00010.jpg



View of sloughing and visqueen on landside levee slope. Spring 2017.

LM Start	2.72	Rating **	A/W	Issue No.	14 (cont)
LM End	2.72	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2019_RD0827_188_14_20190304_00011.jpg



Additional view of sloughing on landside levee slope. Spring 2017.

LM Start	2.75	Rating **	M	Issue No.	5
LM End	2.75	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.641613 °	38.641613 °
				-121.620718 °	-121.620718 °
DWR ID	DWR_RD0827_02_s_2019_5				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					
Vehicle ruts on the crown.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---